CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

Corner common to sections 20, 21, 28, and 29, T. 1 N., R. 6 W., W. M., Tillamook County, Oregon.

ORIGINAL.

Post; now missing, from which a:

15" Hemlock bears S54E 35 lks; now 30" snag, scribe marks visible on edge of burnt face. (Did not expose rest of face).

10" Hemlock bears NSIE 39 lks; now 15" stub bears SSIE 25.7 ft; scribe marks R6W TIN S21 exposed,

40" Larch bears S15W 7 lks; now rotted out.

30" Fir bears N14W 47 lks; now 36" snag, face burnt out.

RESTORATION OF CORNER AND BEARING TREES

Set a 12 x 36 galvanized iron pipe with 3 bronze cap marked "OREGON STATE BOARD OF FORESTRY TIN R6W S20 S21 S29 S28 1951 2311", 22 ft. in ground. Raised mound of rock around pipe, from which a:

19" Fir stub bears S67°30°E 22.1 ft.; scribed TlN R6W S28 BT 2311.

18" Fir snag N12W 24.8 ft; scribed S20 BT 2311. (Distances measured from center of BT's.)

Placed an Oregon State Board of Forestry metal location poster on 30" Hemlock snag BT and marked it: Sec 28 TlN R6W Sec Cor 19.0 ft. N54W.

Dated December 31, 1951.

This corner was restored by

Don D. Davis Assistant Forest Engineer

under my direction.

Present and witnessed by Douglas Stafford Chainman.

109