## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 29,30,31 and 32	TOWNSHIP 2 South	RANG	NGE 10 West		
COUNTY: Tillamook			DATE: 12-18-08		
CORNER DESIGNATION: The Section Corner common to 29, 30, 31					
and 32.	e Section Comer Common to 29, 30,	31		(Please check one)	
4114 02.	Č		H	Condition Report Only Restoration	
			屋		
				Rewitness Unrecorded	
			H	Reset at surface	
			H	· · · · · · · · · · · · · · · · · · ·	
Provinus Rewitnesses Restorations and Surveys ato: DI M Field Not			, , : : : : : : : : : : : : : : : : :		
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0272 Page 0093.0 – 0094.0. GLO 2S10 Pg. 53, 1882, B-78, A-661 located in Tillamook County Survey Records. Corner was restored in Book 2, Page 461 in 1961, Tillamook County Survey Records. This corner has never been rewitnessed.					
Found Monument(s) and Accessories (Condition & Source): Found a 2" inside diameter iron pipe with a lead plug, up 0.3' in good condition. The monument is stamped as shown hereon.  (Book 2, Page 461) – Found original 18" rotten Hemlock Stump, 3' tall, bears N 22° E 19.1', no scribing visible.  (Book 2, Page 461) – Found original 20" rotten Hemlock Stump, 2' tall, bears N 31° W 19.8', no scribing visible.  (Book 2, Page 461) – Found original Hemlock Stump, 3' tall, bears S 64° W 21.4' (S 66° W 23.1' slope), no scribing.  (Book 2, Page 461) – Found original rotten stub, 6' tall and broken off, bears S 27° E 17.8', scribing partially visible.  ( ) Indicates record information from Rewitness Book 2, Page 461, Tillamook County Survey Records.					
	nd Description): Not applicable.			ch of Found Monument:	
			$ \begin{array}{c c}  & 75 & 70 \\ \hline  & 30 & 29 \\ \hline  & 31 & 32 \end{array} $ #376		
New accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around monument. Set the found 4" x 4" White					
Cedar Post at N 78° E 1.8' from corner. Set 72" hat section post with tag at N 10° W 2.0' from corner.					
New Bearing Trees set:  16" diameter Hemlock bears N 78° W 17.8', scribed "T2S R10W S30 BT", tagged and painted.  15" diameter Hemlock bears N 23° E 24.1', scribed "T2S R10W S29 BT", tagged and painted.  14" diameter Hemlock bears S 68° E 16.1', scribed "T2S R10W S32 BT, tagged and painted.  16" diameter Hemlock bears S 31° W 24.5', scribed "T2S R10W S31 BT, tagged and painted.  All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T.					
Location & Comments: Corne North/South running, Whiskey (	er is located approx. 80' West of Creek Mainline logging road.				
Firm / Agency				SURVEYOR'S SEAL	
Address: TILLAMOOK COUN	TY SURVEYOR'S OFFICE				
201 Laurel Avenue Tillamook, Oregon	97141			REGISTERED PROFESSIONAL	
Party Chief: Joe Jensen, P.L.S	6 60067 Survey Supervisor			LAND SURVEYOR	
Tanty Omer 000 concern, Fiz. c	. Cooot, Gaivey Capervisor			Joseph V. Jeusen	
Notes:	D.I. C. 40220 Tillerseels Courts C			OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60067	
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor.  Michael R. Rice, L.S.I. 16723, Survey Technician				RENEWAL DATE: 06-30- 09	
		-		JAN 1200	