



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 25 & 36	TOWNSHIP: 2 South	RANGE: 7 West
COUNTY: Tillamook		DATE: May 11, 2021
CORNER DESIGNATION: The 1/4 corner common to Section 25 and Section 36, Township 2 South, Range 7 West, W.M., Tillamook County, Oregon	(Please check one)	
	<input type="checkbox"/> Condition Report Only	
	<input type="checkbox"/> Restoration	
	<input checked="" type="checkbox"/> Rewitness	
	<input type="checkbox"/> Unrecorded	
	<input type="checkbox"/> Reset at surface	
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc BLM Field Notes: OR -R0345 Page 227; B-3087, Tillamook County Survey Records; Rewitness Book 8, Page 062;		
Found Monument(s) and Accessories (Condition & Source): Found a 2-3/8" brass cap on a 1-1/4" iron pipe per B-3087, level with the surface. This monument was found leaning slightly, likely due to recent logging. I located the 1/2" iron rod subsurface monument set by B-3087 and plumbed the 2-3/8" brass cap over it. Distances to bearing trees were measured to existing nails at side center. Found 19" Douglas Fir stump, 6 feet tall, with a healed face, bearing S28°W 58.83' (S28°W 58.90' per B-3087) Found 14" Douglas Fir stump, 6 feet tall, with a healed face, bearing S33°30'E 26.40' (S32°30'E 26.35' per B-3087) The other two Douglas Firs marked by B-3087 bearing N74°W 29.70' and N04°W 34.00' were found uprooted, destroyed entirely by logging.		
Monument Set (Procedures and Description): No new monument was set. The brass cap and pipe previously established by B-3087 was reset over the 1/2" iron rod subsurface monument. An orange carsonite paddle was set alongside.	Pictures of Found Monuments: 	
New accessories set: Set a 5/8"x30" iron rod reference monument with a yellow plastic cap marked "Stuntzner Eng." bearing N53°30'E 48.42'. An orange carsonite paddle was set alongside. Set a 5/8"x30" iron rod reference monument with a yellow plastic cap marked "Stuntzner Eng." in a 24" Douglas Fir stump bearing N58°30'W 65.52'		
New Bearing Trees set: No new bearings trees were available near the monument		
Location & Comments: The monument is located on a ridge approximately 58 ft. south of the centerline of a gravel logging road.		SURVEYOR'S SEAL REGISTERED PROFESSIONAL LAND SURVEYOR  OREGON July 12, 2005 Corey M. Woodruff 62978 EXPIRES 6/30/22
Firm / Agency Address: Stuntzner Engineering & Forestry 2318-B Pacific Ave. Forest Grove, OR 97116		
Party Chief: Corey M. Woodruff, PLS 62978		
Notes:		
Witnesses: n/a		

