

No. U-25 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____

S.S. R. LOW RD. HEBO County TILLA # 911

id. WILL N.F. SIUSLAW State ORE.

DIAGRAM DESCRIBE CORNER MONUMENT FOUND

FOUND 2X3X10 SPRUCE LIMB IN POOR CONDITION. "CS" IS SCRIBED ON ITS SIDE. A 3/4" GALVANIZE PIPE SETS ALONG - SIDE.

DIAGRAM: A square with "25" in the center, a circled "X" at the bottom right, and "EAST = S 1/8" written below it.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 2.5" ALDER, S. 21° W., 33± FT. WITH VISIBLE BARK SCRIBES "S 1/8 S 25 BT."

I SET IRON FENCE POST ALONGSIDE CORNER WITH PENALTY TO DESTROY AND BOUNDARY SIGNS ATTACHED.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature: Leonard Whitmore Title: Forestry Tech Division: Timber Date: 7-3-75

Agency: _____

REWITNESS

I SET

"x	"x	" Post	N. W.	feet
" Hat Section			S. E.	

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF:

DATE: _____ PHOTO#: _____ TITLE: _____

* - County corner tag affixed.