

T. L. N. R. 6. W.

C

I/4 Cor. on W. line of Sec. 6 T. I N. R. 6 W.
Original Hemlock N. 55° E. 3.3 links is down and blaze is burnt out. Two B. T. set by Anderson have scribing burnt out. I rescribe fir (I/4 B. T.); Hem. is too rotten to mark. Had no instruments, but scribed a 40" cedar (I/4 B. T.). It is a line tree as near as we could judge looking north toward the section cor. and is 38.5' from the cor.

2/4/43

T. I & 2 N. R. 6 W.

C

Sec. Cor. 31* 32- 5- 6 T. I & 2 N. R. 6 W.
Set con. monument with brass disk stamped Sec. Cor. 31-32-5-6 T. I&2 N. R. 6 W. Cor. falls in North shoulder of hwy. and is buried about 8 inches. A concrete B. M. with O. S. H. D. standard disk is set eight feet North of Cor. for reference.

6/10/42

WHAT?
SEC.

I/16 Cor. N. W. Cor. of N.E. I/4 of N.E. I/4
Set 40" piece of Inch & a quarter pipe 30" in ground. B. T.
36" Fir stump S. 62° E. 9.3'; marked I/16 B. T. This Cor. was set by State Highway Engineers.