CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 19 and 24, T2N, R9-10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing,

20" Hemlock bears N15°W 10 lks.; now missing, remains of ancient road through position.
18" Hemlock bears S50°E 17 lks.; now 10" 3 ft. high stub,

portion of scribe remaining.

## RESTORED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY \( \frac{1}{4} \) \$24 \$S19 1955 RE2311," 34 inches in ground, in mound of river boulders, and from which a:

12" Hemlock bears S62°E 11.8 ft.; previously scribed \$\frac{1}{4}\$ S19 BT (about 10 years old), by parties unknown.
23" Spruce bears \$49°W 17.8 ft.; scribed \$\frac{1}{4}\$ \$24 BT RE2311

Reset 4"x4"x36" old white Cedar post 1.5 ft. NW of pipe.

Oregon State Board of Forestry metal location poster on 12" Hemlock BT.

Oregon State Board of Forestry metal location poster on 23" Spruce BT.

Poster on 4"x4"x48" white Cedar post 678.0 ft. South on South edge log road.

Dated May 3, 1955.

Restored by <u>Gradd & Selsan</u> under my direction.

Arnold G. Gibson, Assistant Engr.

Vorus W. AMOR

Present and witnessed by Lloyd Geraths.

Book I