CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 30 and 31, T3S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

(no evidence of original corner found)

RESTORED 1887 (see county records) Hays Book F" Page 78

(no evidence of restored corner found)

RESTORED by W. E. Anderson June 30, 1949 BK 4 Page 58 \$ 8k1 Page 8

1" iron pipe 6" below ground (now missing) $2\frac{1}{2}$ " $x2\frac{1}{2}$ " wooden stake (found down with scribes $\frac{1}{4}$ on side) from which a:

8" Apple tree bears S8220W 185.0 ft.; now missing. 30" Spruce bears S12°W 156.2 ft.; now 28", face grown over.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze csp marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S30 S31 1957 RS 359," 36 inches in ground, in mound of stone, and from which a:

Original 30" spruce bears S12°W 156.2 ft.; scribed BT. 28" Fir bears N45°E 247.0 ft.; scribed \(\frac{1}{4}\) S30 BT RS 359.

Oregon State Board of Forestry metal location poster on fir BT.

Set 4"x4"x60" white painted Cedar post 2.0 ft. NW of pipe.

Pipe is 18.7 feet W of U.S. 101 centerline and 3.0 feet East of fence corner.

Dated February 21,

under my direction. Restored by Richard Morris, Transitman

REGISTERED OREGON LAND SURVEYOR

> ARNOLD G. GIBSON 359

(1972) RESTORED Present and witnessed by Lloyd Geraths

Robert Sturm Set 3" Brass Cap over Fd Forestry Cap morder to bring corner up to present ground level. Corner is in concrete and tile. Corner 15 now in pavement of U.S. #101

G.W.U., 1972

Book I