CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner for E. boundary of Section 27, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

24" Hemlock bears N30W 29 lks.; now 18" badly decayed uproot, roots in place, pointed out by Harold Williams (see affidavit filed in Tillamook County Surveyor's office).

5" Hemlock bears S45E 42 lks.

RESTORED

Var. 21 E

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S27 1959 RS401", 30 inches in ground, in mound of stone, and from which a:

14" Hemlock bears N40W 1.9 ft.; scribed 1/4 S27 BT RS401.

Oregon State Board of Forestry metal location poster on 14" Hemlock BT. Set 4" x 4" x 54" white painted Cedar post 1.3 Ft. S.E. of pipe.

Dated February 19, 1959

Restored by

REGISTERED
OREGON
LAND SURVEYOR

Richard A. Marris
401

Present and witnessed by Harold Williams Harold Russell

Robert Cop

Book I

357

78

AFFIDAVIT

State of Oregon County of Tillamook

I, Harold Williams , of Bay City, Oregon,
being first duly sworn, do depose an say as follows:
I am fifty-seven years old and have been a timber cruiser for the
last 35 years. I saw the one quarter corner for the east boundary
of section 27, T.25. R.9W.W.M., in 1926 while working for the
Whitney Co. Ltd. I saw scribes on a hemlock uproot that beared
to the north west of the corner point. I have visited the corner
six times since and the scribes were rotted off of the hemlock
uproot. The bearing tree was close to a blazed north and south
line which is still visible, and was also situated on a small spur
ridge which is in place. I pointed out the above bearing tree to
Richard Morris who set a l_2^{1} x36" galvinized iron pipe with a 3"
bronze cap, furmished by the Oregon State Board of Forestry, S30E
19.1 feet from the above pointed out hemlock uproot.

Harold Williams

STATE OF OREGON)ss

On this 26th day of February 1959 before me the undersigned, a Notary Public in and for said County and State personally appeared the within named Harold Williams who is known to me to be the identical person described in and who executed the within instrument.

Notary Publicy for Oregon
My Commission expired 9/10/62

Book I

361