CHAINS RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY Section corner common to Sections 13, 14, 23 and 24, TlN, RlOW, W.M., Tillamook County, Oregon. ORIGINAL Post (missing) from which a: 10" Hemlock bears SlOE 12 lks.; now missing, root hole in place.
20" Hemlock bears SlOW 19 lks.; now 30" uproot, root hole in place, scribes S23 visible. 14" Hemlock bears N31W 18 lks.; now missing. RESTORED October 4, 1886 by Hayes Post (missing) from which a: Hemlock bears N47E 26 lks.; now 24" uproot face down, root hole in place. RESTORED Var. $2l_{\overline{2}}$ E Set 1 x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TIN RIOW SLA SL3 S23 S24 1959 RS401", 31 inches in ground, and from which a: 16 Hemlock bears S47W 14.7 ft.; scribed T1N R10W S23 BT. 48" Hemlock bears S18E 75.2 ft.; scribed TlN RlOW S24 BT RS401.
8" Hemlock bears N46E 22.6 ft.; scribed TlN RlOW S13 BT. 14 Hemlock bears N5W 33.2 ft.; scribed T1N R1OW S14 BT.

Oregon State Board of Forestry metal location poster on 16" Hemlock BT. Set 3" x 4" x 52" white painted Cedar post 1.0 foot N.E. of pipe.

Dated August 4, 1959

Restored by

REGISTERED
OREGON
LAND SURVEYOR

MAY 10 1917
Richard A. Months
401

Present and witnessed by H. Russell

R. Cop

E. Nylund

D. Jones

BOK I

399

39