

South $\frac{1}{4}$ corner, Sec 33, T4N, R10W Notice of re-witness.

The first government survey made the corners common to sections 33, T4N, and 4, T3N. The later survey made double corners, and this corner was designated as the corner to Section 33 only. The notes call for a stake corner,

B T's a Larch 36" N 56* E 24 Links.
Hemlock 24" S 14* W 20 links.

Both of these trees are still standing, with all marks plain, but they are both dead and liable to be obliterated by logging; therefore, I made additional witnesses:

Star drilled a $\frac{3}{4}$ " hole 2" deep in a rock outcrop, about 7 feet east of a creek flowing south; in the hole drove solidly a $\frac{1}{2}$ " galvanized pipe, 14" long; yellow paint on pipe and rock. It bears from the corner N $80\frac{1}{2}$ * E 79.0 feet.

Star drilled a $\frac{3}{4}$ " hole in the sharp ridge top of a rock outcrop; drove in solidly a $\frac{1}{2}$ " galvanized pipe 14" long; yellow paint on pipe and rock. It bears from the corner S $51\frac{1}{2}$ * W, 38.25 feet.

A live hemlock, 36" diameter, bears S 78* E 25.5 feet, scribed:
" $\frac{1}{4}$ S 33 BT 1842"

At the ^opint for the actual corner, placed a $\frac{3}{4}$ " galvanized pipe 4 feet long, 2 feet in ground; painted yellow.

Done June 7, 1962, in the presence of D. T. Callahan.

W A Markham
Registered Engineer No. 1842.

(As this corner is on the county line, this report is being filed in the county surveyor's offices of both Clatsop and Tillamook Counties.)

