

County Surveyor's Record, Tillamook County, Oregon

	CHAINS	T3S R10W
29	28	<p>EVALUATION AND RESTORATION OF LAND SECTION CORNERS</p> <p>$\frac{1}{4}$ Corner common to Sections 28-29, W.M., Tillamook Co., Oregon</p> <p>ORIGINAL:</p> <p>Set post $\frac{1}{4}$ ft. long, 6 ins. diam., 12 ins. in ground for $\frac{1}{4}$ sec. cor., mkd. $\frac{1}{4}$ S on W face; from which</p> <p>Fir, 18 ins. diam., bears N.80°W., 113 lks. dist., mkd. $\frac{1}{4}$SBT.</p> <p>Hemlock, 10 ins. diam., bears N.10°E., 122 lks. dist., mkd. $\frac{1}{4}$SBT.</p> <p>FOUND:</p> <p>45" Fir, N.80°W., 74.6 ft. as original notes. Sawed into this tree and found visible mks. "$\frac{1}{4}$SB". The original 10" Hem., N.10°E., 80$\frac{1}{2}$ ft. is entirely gone. A creek is 1.25 chains North as in original notes.</p> <p>RESTORED:</p> <p>Set 1" pine 30" above ground, and mark one new BT as follows:</p> <p>16" Hem., S30°E., 13 ft. mkd. $\frac{1}{4}$S28CSBT.</p> <p>DATED: 1-16-67</p> <p>RESTORED BY: Leonard Whitmore, Till. Co. Deputy Surveyor</p> <p>WITNESSED BY: Jim Rogers Frank Ferguson</p>