

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Standard Section corner common to Sections 33 and 34,
Township 5 South, Range 9 West, W. M., Tillamook and
Yamhill Counties, Oregon.

ORIGINAL

Post (now missing; found 1/2" iron pipe in place) from which a:

4" Hemlock bears N 78 W 54 lks.; missing.

5" Fir bears S 48 E 15 lks.; missing.

6" Fir bears S 44 W 18 lks.; missing.

Original blazes found North of this corner and South of the
Section corner 3 and 4 which is 15 links West. (Caudle 1880).
Ridge, E and W, South 4.50 chains; in place.

RESTORATION by Tillamook County Surveyor in 1887.

Post (missing, found above 1/2" pipe) from which a:

40" Fir Snag bears N 40 E 15.0 ft.; now 39", scribes T5S
3 visible on burnt face.

36" Fir Snag bears N 23 W 18.5 ft.; now 40" snag, scribes
T5S visible on burnt and weathered face.

RESTORATION by Mervin Whitmore 1958, 1/2" iron pipe (found)

RESTORED

Var 21 1/2 E

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NW of corner pipe
from which a:

40" Fir Snag (CS BT) bears N 20 W 19.3 ft.; scribed BT.


39" Fir Snag (CS BT) bears N 38 1/4 E 14.5 ft.; scribed T5S,
R9W, S34 BT RS707.

Corner is on a broad ridge that slopes N 10 E.


Oregon State Forestry Department metal location poster on 40" Fir
Snag BT.

Dated June 26, 1968.

Restored by



Harold J. Russell



Present and witnessed by B. Harris