

TILLAMOOK COUNTY SURVEYORS OFFICE
COURT HOUSE, TILLAMOOK, OREGON 97141

C 1/4 CORNER SECTION 23, T.1N., R.10W., W.M.

C 1/4 I found a 1 1/2" iron pipe with a 3" Oregon State
Board of Forestry Bronze Cap, (see T.C.S. Map
S 23 #B-419), bent and out of position, I straightened
CS RESET 1992 and reset in found hole. I added "CS RESET 1992"
1959 to the cap and encased the found Iron Pipe in a 10"
RS 401 concrete cylinder.

History of found monument

I found this monument to be as described on said T.C.S. Map and the references found and/or set at that time to now be as follows:

(Map #B-419) 20" spruce N.21°E. 34.1'; (Gone, position on Easterly edge of creek).

(Map #B-419) 17" spruce S.3°E. 35.4'; (Found, now a rotten 17" stump 2' high, scribing visible on small portion of remaining face).

Found white cedar post rotted off and laying alongside of corner position.

New Accessory

*72" light hat section post S.70°W. 8.0'.

*5" Alder N.17°E. 16.05', scribed "C1/4S23BT". The distance was measured to a nail with brass washer between the scribed B & T.

5/8" iron rod with yellow plastic cap inscribed A. Duncan LS 793 bears N.4°W. 85.12'.

*indicates Tillamook County Surveyors yellow metal location poster attached.

Surveys and Rewitnesses of record

B-419	12-31-59	Richard A. Morris	RS 401
Rewitness Book 2 page 421	12-31-59	Richard A Morris	RS 401
B-901	Apr. 1980	C. Wayne Cook	LS 1098


Location of Monument

This corner is located approximately 20' Westerly of a creek 5' wide, course N.45°W., in an old cat road.

In the presence of Al Dvorak and Dan McNutt

May 14, 1992

Title



Allan E. Duncan, C.S.

