

RESTORATION OF THE QUARTER CORNER COMMON TO

SECTIONS 16 AND 21, T3N, R10W, W.M.

At the corner I find the base of an old spruce limb post stuck in the ground, the top portion of which has rotted off and is lying along the north side thereof. Faint scribe marks "1/4" are visible on said top portion. From said post the original B.T.'s scribed by C. J. Handley in September 1873 bear as follows: The 20" hemlock at S 40° W 4 links is now a rotten 2' tall 28" hemlock snag that bears S 40° W 2.6 feet to back cast of old face with portion of original reverse scribed "T" visible. The 14" hemlock at N 48° W 38 links is no longer present, but in vicinity of reported position I find a rotten log with overgrown cruiser's mark. The 24" hemlock set by P. L. Thompson on February 16, 1951, and recorded in County B.T. Record Book 2, Page 116, at S 76° 50' W 20.4 feet is now a 32" hemlock stump that bears S 77° W 20.4 feet to rotten face with scribe marks visible. I remove base of old post and in its place I set flush with ground a 2" x 36" concrete filled galvanized iron pipe with a 3" brass cap stamped "T3N R10W 1/4 S16 S21 1996 LS 849" from which I scribed the following B.T.'s: A 19" fork-topped spruce bears N 71° E 22.9 feet to 8" spike below face scribed "1/4 S16 B.T." A 14" hemlock bears S 33° E 13.00 feet to 8" spike below face scribed "1/4 S21 B.T." A 20" hemlock bears S 62° W 24.35 feet to 8" spike below face scribed "1/4 S21 B.T." A 27" hemlock bears N 67° W 11.93 feet to 8" spike below face scribed "1/4 S16 B.T." Set steel fence post with location tag 3 feet east. No trace of 3/4" iron pipe reported as set by P. L. Thompson on County Survey B-299.

PRESENT: K. FOESTE, A. HOFMANN, AND L. HOFMANN

DATE: June 21, 1996



RENEWS 1/1/98