

BAYSIDE SURVEYING

11765 HWY 101 South
Tillamook, Oregon 97141

Terry L. Jones
503-842-5551
Fax 503-842-5552

June 2003

REWITNESS

¼ CORNER COMMON TO SECTIONS 1 and 36
TOWNSHIPS 2 and 3 SOUTH, RANGE 8 WEST

I Found:

OSBF brass cap stamped "T2S R8W ¼ S36 S1 T3S R8W 1975 RS 707" on 1 1/2" iron pipe, on gentle West slope approximately 69' West of top of ridge, approximately 220' East of Creek. (See MAP B-714)

From which:

50" Fir stump with scribing "1/4 S1 BT RS707" visible, bears S86 1/2°E 22.5'. (50" Fir stump S86½°E 22.5'. See MAP B-714)

45" Fir stump with location tag and scribing "1/4 S1 BT" visible, bears S11 1/4°E 95.4'. (45" Fir stump S11 1/4°E 95.4'. See MAP B-714)

White 4" x 4" post 1' SW. (See MAP B-714)

I set:

A 5' steel posts 1' East and West, and 2 new references as follows:

11" Douglas Fir scribed "1/4 S36 BT" bears N0° 12' 32" W 12.39' to brass nail & washer stamped "LS 2507" between the B & T;

Set 5/8" x 40" rebar with yellow plastic cap marked "TERRY JONES LS 2507", with steel post 1' East, on top of ridge, bears S89° 33' 57"E 60.84' ;

In the presence of Terry Jones, Dallas Esplin

