

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: Located in the SE 1/4 of Section 24	TOWNSHIP 1 South	RANGE 9 West	
COUNTY: Tillamook		DATE: 05-15-07	
CORNER DESIGNATION: The Center-East 1/16 corner of Section 24, Township 1 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
		<input checked="" type="checkbox"/>	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: See survey maps A-530 and A-5086.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Oregon State Board of Forestry Brass cap on a galvanized iron pipe in dirt and loose rock on a steep, Easterly facing slope. White painted cedar post is gone. Found a large rotted stump (at the record location of a 54" diameter hemlock bearing tree as described on map A-530) with several trees growing out of stump, no visible scribing and no yellow metal location poster. Found a rotten Hemlock stump with visible scribe marks at the record location of a 40" diameter Hemlock bearing tree as described on map A-530.			
Monument Restoration (Procedures and Description): Set a 12" diameter plastic cylinder and 120 pounds of concrete around found Brass Cap and pipe. Also placed stones around the outside of the plastic cylinder.	Sketch of Set Monument::		
New accessories set: **Set a 72" light hat section post 1.3' East of corner.			
New Bearing Trees: **9" diameter Spruce tree scribed "CE 1/16 S24 BT" with a nail and brass washer stamped "TC SURV" set between the scribed 'B & T' which bears North 70° West 13.18 feet. **16" diameter Hemlock tree scribed "CE 1/16 S24 BT" with a nail and brass washer stamped "TC SURV" set between the scribed 'B & T' which bears South 42° East 19.56 feet. ** Indicates yellow metal location tag set with corner accessory.			
Location & Comments: This corner is located approximately 100 feet East of an old landing and 55 feet West of an 18" wide creek with a course of North 8° West.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE		SURVEYOR'S SEAL RENEWAL 12-31-2008	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor			
Notes:			
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor			

