



OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 1	TOWNSHIP: 2 North	RANGE: 10 West
COUNTY: Tillamook		DATE: 8/20/2007
CORNER DESIGNATION: Northwest corner of Section 1		(Please Check One)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.: Book 6, Page 49 Map B-1799 and map B-736		
Found Monument(s) and Accessories(Condition & Source): Found CZ brass cap with steel post 1 foot North and 38" rotted stump with location tag which bears (S 30-15 E 35.25') Other 2 "stubs" are rotted and/or gone.		
Monument Set(Procedures & Description): Monument in good condition		
Other New Accessories Set: Set second Steel Post 3 Feet East Also attached yellow "GREEN DIAMOND" property line tags on both post, painted tops red and hung orange flagging.		
New Bearing Trees: Marked 4 new bearing trees as indicated (SE BT is in the NE Quadrant) 13" hemlock scribed "T3NR10WS36B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears North 43 East 34.85 feet. 14" hemlock scribed "T2NR10WS1B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears North 87 East 44.57 feet. 10" hemlock scribed "T2NR10WS2B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears South 16 West 24.37 feet. 11" spruce scribed "T3NR10WS35B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears North 74 West 13.99 feet.		
		Surveyor's Stamp
Firm/Agency: Bayside Surveying		
Address: 11765 Hwy. 101 South Tillamook, OR 97141		renewal date 6-30-09
Party Chief: Terry L. Jones		
Notes: in 2N 9 6 file in office		Office Use Only
Witness(es): Dallis Esplin		