

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: Southeast corner Section 17	TOWNSHIP 1 South	RANGE 7 West
COUNTY: Tillamook		DATE: 02-01-08
Corner Designation: The section corner common to Sections 16, 17, 20, 21, Township 1 South, Range 7 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Not found
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Book 7, Page 8, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found 3" diameter brass disk in good condition and stamped as shown hereon. Placed 60 pounds of concrete around found monument. All four bearing trees set in 1990 and as described in Rewitness Book 7, Page 8 were found at record positions with healed faces.		
Monument Set (Procedures and Description): Not applicable.		Sketch of found Monument:
Other new accessories set: Set a 72" hat section post with yellow metal location tag North 2.6'		
New Bearing Trees: No new bearing trees were marked.		
Location & Comments: This corner is located approximately 800' North of road and 50' East of a quad trail.		
Firm / Agency: Address: Tillamook County Surveyor's Office 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div>
Notes:		
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2006 JOSEPH V. JENSEN 60067 </div>
		<i>RENEWAL DATE: 06-30-09</i>



BOOK 7 435