

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The Southeast corner of Section 3	TOWNSHIP 2 South	RANGE 10 West
COUNTY: Tillamook		DATE: 10-15-08
CORNER DESIGNATION: The section corner common to Sections 2, 3, 10, 11, Township 2 South, Range 10 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
Previous Rewitnesses, Restorations and Surveys, etc.: Rewitness Card #435; AMA Book 14, Page 76; Rewitness Book 1, Page 407; Survey maps B-555; B-562; A-860; Tillamook County Survey Records.		<input type="checkbox"/> Reset at surface
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Crown Zellerbach Brass cap upright and in good condition at the base of an uprooted 22" diameter Douglas Fir bearing tree (12" Douglas Fir tree on Rewitness Card #435). I cut the 22" Fir at the root to expose the corner. The cap is stamped as shown hereon. Found a damaged hat section post, approximately 1' above ground under the 22" uproot.		<input type="checkbox"/> Referenced Out
<p>Found an 8' tall Spruce snag 16" in diameter with healed face (10" Spruce tree on Rewitness Card #435). Found a rotten stump (was a 40" diameter stump on Rewitness Card #435), at record position. Found rotten remains (was a 30" diameter rotten stump on Rewitness Card #435), at record position. Found a rotted stub (was a stump 7' to 10' high on Rewitness Card #435), at record position. Found a rotten remains (was an 18" diameter rotten stump on Rewitness Card #435), at record position.</p>		
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument:	
New accessories set: Set a 72" hat section post 3 feet North 58° East of corner monument. Results of GPS observation = NAD 1983/91 Oregon State Plane Coordinates, U.S. Foot, Northing = 657429.046, Easting = 7332862.835, Ortho Elev. = 54.802 1988 NAVD.		
New Bearing Trees: No new bearing trees set.		
Location & Comments: This corner is located at the base of an uprooted 22" diameter Douglas Fir tree and at the top edge of an embankment on the south side of a swamp, approximately 400' South of Ekloff Road.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes:		
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor.		