## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT **Tillamook County Surveyor's Office**

SECTION: The 1/4 corner of TOWNSHIP 2 South RA			NGE 10 West	
COUNTY: Tillamook		<u> </u>	1	DATE: 11-06-08
	e Quarter Corner common to Section	ns 3		(Please check one)
and 4, Township 2 South, Range 10 West, W.M., Tillamook County,				Condition Report Only
Oregon.				Restoration
			×	Rewitness
				Unrecorded
				Reset at surface
				Referenced Out
Previous Rewitnesses, Resto original NE Bearing Tree on n		j. 14, 2S	107	/ 1857, 1/4 section corner set from
concrete, 0.20 feet below the su (Map B-659) – Did not find the 4 (Map B-659) – Did not find the 4 (Map B-659) – Found 18" (was	urface. The monument is stamped a 40" diameter Hemlock Stump at rec	s shown ord posit .87 Feet	n here tion. , Sca	ır Visible. Tagged.
Monument Set (Procedures a	nd Description): Not applicable.	7 5	Sketo	ch of Found Monument:
				S4 S3
	0" hat section post with yellow meta section corner using control set with			
	3° W 12.61 Feet, Scribed "T 2 S R 1 E 3.65 Feet, Scribed "T 2 S R 10 V			
Location & Comments: This c an old grown over rock logging	orner is located approximately 30' V road.	Vest of		, <del>omak yanini waxanini dhakala in Chakali in Kaladi in Chakali in Kaladi in Chakala in </del>
Firm / Agency Address: TILLAMOOK COUN 201 Laurel Avenue Tillamook, Oregon			S	URVEYOR'S SEAL
Party Chief; Joe Jensen, P.L.S Notes:	. 60067, Survey Supervisor			PROFESSIONAL LAND SURVEYOR
Witnesses: Danny R. McNutt, I Surveyor: Michael R. Rice, L.S.	P.L.S. 49230, Tillamook County I. 16723, Survey Technician			OREGON JULY 11, 2000

RENEWAL12 - 31- 2008