

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 32, 33	TOWNSHIP 2 North	RANGE 6 West
COUNTY: Tillamook		DATE: 11-19-08
CORNER DESIGNATION: The Quarter Corner common to Sections 32 and 33.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: GLO Pg. 35, 2N 6W 1857, Quarter corner set from original SE Bearing Tree by 199 in Book 2, Page 9.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Brass Cap in good condition, protruding 1.0 Feet above ground. Rotated Cap North. The monument is stamped as shown hereon. (G.L.O.) – Found 26" diameter, 5' tall, rotten stump at S 41°15' E 23.1 Feet. (G.L.O.) – Did not find the 10" diameter Hemlock at record position. (Bk. 2, Pg. 9) – Found 45" diameter, 5' tall, rotten stump at S 12° W 59.8 Feet.		
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument:	
New accessories set: Set a 72" hat section post with yellow metal location tag South 4.0 feet from corner position. Set the Found 72" X 6" X 6" White Cedar Post East 4.0 feet from corner position and painted pink. Set 60 lbs. of concrete in a 12" diameter plastic cylinder around corner. All new bearing trees have a nail and washer marked, "Till. Co. Surveyor", in face of blaze.		
New Bearing Trees set: 26" diameter Fir bears S 74° E 15.4 Feet, Scribed "T2N R6W 1/4 S33 BT", Tagged, Painted. 19" diameter Fir bears S 19° W 39.4 Feet, Scribed "T2N R6W 1/4 S32 BT", Tagged and Painted.		
Location & Comments:		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		
Notes:		
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

