

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 4	TOWNSHIP 3 North	RANGE 9 West	
COUNTY: Tillamook		DATE: 4-29-11	
CORNER DESIGNATION: The Section Corner common to Sections 5, 4, 8, and 9, T. 3 N., R. 9 W., W.M.		(Please check one)	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0259 Pages 156-157 (1881); BLM Field Notes Volume: OR-R0373 Page 18 (1893); (GLO 3N9W Pg. 81) (1881), Book 2, Page 591 (1965); Maps B-502, B-510, B-597, Tillamook County Survey Records.			
Found Monument(s) and Accessories (Condition & Source): Found a 3" Oregon State Board of Forestry brass cap in upright and in good condition. Set a 12" diameter plastic cylinder and 120 pounds of concrete around the found monument. Northing = 783580.769, Easting = 7359543.130, '83-'91 NAD, U.S. Survey foot, Oregon North Zone State Plane Coordinates. The monument is stamped as shown hereon. Found a partially rotten white post lying on the ground next to monument. Found following bearing trees: (GLO Original 1881) – Found a rotten shell of a 3' tall stump with no scribing visible at record position (10" Hemlock which bears S45°W 57 links GLO 1881); (42" Hemlock stub 6 ft. high scribe 'B' on lower face found inside, upper face rotted away bears S45°W 57 links Rewitness Book 2, Page 591). (Book 2, Page 591) – Found a 26" diameter Hemlock tree with a healed face and yellow location tag at record position (was 14" Hem. Bears N9 3/4° W 5.4' scribed T3N R9W S5 BT RS401). (Book 2, Page 591) – Found rotten remains with no visible markings at record position (was 13" Hem. Bears N68° E 20.9' scribed T3N R9W S4 BT). (Book 2, Page 591) – Found a 25" diameter uproot lying nearly on top of the found monument. The Hemlock uproot was cut just above the yellow location tag and healed face, and the stump then sprang nearly upright after the tree was cut (was 14" Hem. Bears S6 1/2° E 9.5'; scribed T3N R9W S9 BT). (Book 2, Page 591) – Found a 17" diameter, 20' tall Hemlock snag with a healed face at record position (was 8" Hem. Bears S83° W 12.3' scribed T3N R9W S8 BT).			
Monument Set (Procedures and Description): Not applicable.		Sketch of Found Monument:	
New accessories set: Set a 72" Hat Section Post 3' South of monument. Set a 5/8" X 30" rebar with a red plastic cap stamped "Tillamook Co. Survey" as a reference accessory to the corner monument. This 5/8" rebar with Tillamook County red plastic cap bears South 61° 30' West 29.87' from corner monument. Northing = 783567.174, Easting = 7359516.528, '83-'91 NAD, U.S. Survey foot, Oregon North Zone State Plane Coordinates.			
New Bearing Trees set: *12" diameter Hemlock bears N 61° 30' E 28.2', scribed "T3NR9WS4BT", tagged and painted. *22" diameter Hemlock bears S 38° W 64.4', scribed "T3NR9WS8BT", tagged and painted. * Indicates yellow metal location tag affixed to new bearing tree. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T.			
Location & Comments: Corner is located approx. 200' South of a gravel logging road in blow-down area.			
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> REGISTERED PROFESSIONAL LAND SURVEYOR </div> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067 </div>	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		RENEWAL DATE: 06-30-2011	

Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor

Notes: Digital images were taken of the corner monument and corner accessories. The monument and 5/8" rebar with red plastic cap were conventionally field tied using GPS established control. The coordinates are '83-91 NAD, U.S. Survey Foot, Oregon North Zone State Plane.

Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor.
Michael R. Rice, L.S.I. 16723, Survey Technician

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Joseph V. Jensen

OREGON
JANUARY 10, 2008
JOSEPH V. JENSEN
60067

RENEWAL DATE: 03-30-2011

