

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION 30	TOWNSHIP 5 South	RANGE 10 West
COUNTY: Tillamook		DATE Dec. 27, 2006
CORNER DESIGNATION: Center-South 1/16 corner of Section 30.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Not Found
		<input checked="" type="checkbox"/> Renewed
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Surveyed In
		<input type="checkbox"/> Referenced Out
<p>Previous Rewitnesses, Restorations and Surveys, etc. Map A-4104 (John Carlich) subdivides the SW ¼ of Section 30, Setting the Center-South 1/16 corner. John set a 5/8" rebar on the South side of a forest road and gives coordinates to two ½" rebars at the Pl's of the forest road(references to the 1/16 corner).</p>		
<p>Found Monument(s) and Accessories (Condition & Source): I found a 5/8" x 30" rebar on the South side of the forest road, in the fill slope of the road, leaning Southerly. I also found 2 ½" brass cap on 2" galvanized iron pipe(South ¼ corner Section 30), top 0.3' above ground with steel post 5 feet South and West, 18" Hem. With healed face bears (S 23° E 9.3') and 18" Hem. With healed face bears (N 22° E 21.3'); bears South 8° 55' 24" East 1221.97 feet(South 8° 55' 24" East 1222.03 feet) from Center-South 1/16 corner. () indicates record information from map A-4104.</p>		
<p>Monument Set (Procedures and Description): I replaced with a 5/8" x 40" rebar with yellow plastic cap marked "TERRY JONES LS 2507", top 1 foot below ground, at the position of the bottom of the found monument. I placed a new steel post, top painted red, with a yellow plastic "GREEN DIAMOND RESOURCE COMPANY PROPERTY LINE" tag and an aluminum location tag three (3) feet North of the CS 1/16 corner.</p>		<p>Sketch of Found Monument:</p> <p align="center">TERRY JONES LS 2507</p>
<p>Other new accessories set: I placed a 5/8" x 40" rebar with yellow plastic cap marked "TERRY JONES LS 2507", top 0.5 foot below road surface, at the Pl of the road, approximately 2 feet South of the centerline, at the position of a found ½" rebar(badly rusted and bent), bears North 74°55' 34" West 22.42 feet (N 75°46'07" W 22.09'). I also set another 5/8" x 40" rebar with yellow plastic cap marked "TERRY JONES LS 2507", top 0.5 foot below road surface, 8 feet South of the centerline of the road, bears North 27° 07' 37" West 12.94 feet.</p>		
<p>New Bearing Trees – area to be logged soon, therefore, I did not mark any bearing trees.</p>		
<p>Location & Comments: The corner lies in the fill slope of the lower forest road, approximately 900 feet Westerly from where the road crosses Hawk Creek.</p>		
<p>Firm / Agency Bayside Surveying Address: 11765 Hwy. 101 South Tillamook, OR 97141 Party Chief Terry Jones Notes in private file folder labeled 5S 10 30 Witness Greg Cickavage, Ray Jones, Todd Josi</p>		<p>SURVEYOR'S SEAL Renewal date: 6-30-07</p> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p align="center">REGISTERED PROFESSIONAL LAND SURVEYOR</p> </div> <p align="center"><i>Terry L. Jones</i></p> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;"> <p align="center">OREGON JULY 25, 1991 TERRY L. JONES 2507</p> </div>

