

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> Southeast corner of Section 22	<b>TOWNSHIP 1 South</b>	<b>RANGE 9 West</b>
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 01-18-13
<b>CORNER DESIGNATION:</b> Section corner common to Sections 22, 23, 27, and 26, Township 1 South, Range 9 West, W.M.	<b>(Please check one)</b>	
	<input type="checkbox"/>	Condition Report Only
	<input type="checkbox"/>	GPS Session
	<input checked="" type="checkbox"/>	Rewitness
	<input type="checkbox"/>	Unrecorded
	<input type="checkbox"/>	Referenced Out
<b>Previous Rewitnesses, Restorations and Surveys, etc.:</b> Rewitness Card #215; Rewitness Book 4, Page 65; Rewitness Book 5, Page 121; Tillamook County Survey Records.		
<p><b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 3" diameter Tillamook County Brass cap in a 10" clay tile and cement. Placed a 10" diameter cast iron monument case around the found monument. Filled and placed 120 pounds of concrete around the monument case. The cap is in good condition and stamped as shown hereon. Two - 2" diameter Tillamook County Brass caps were set as reference points to the corner monument due to the absence of record bearing trees. They were both set in 60 pounds of concrete.</p> <p>Book 5, Page 121 (1965,1970) – 4x4x48 white post is now gone.</p> <p>Book 5, Page 121 (1965,1970) – 24" diameter Cedar tree which bears S86°E 72.67' is now gone..</p> <p>Book 5, Page 121 (1965,1970) – Power pole #25 N45°W which bears 20.10' is now gone.</p> <p>Book 5, Page 121 (1965,1970) – 24" diameter twin Spruce tree which bears S63°W 43.4' is now a 40" diameter by 8' tall stump covered in ivy.</p> <p>Book 4, Page 65 (1965,1970) – 10" diameter Alder tree which bears S45°W 44.9' is now gone.</p> <p>Double -occupied GPS observations have been obtained for this corner position and the two reference monuments. The coordinates are provided here in WGS84, Latitude and Longitude. Latitude: North 45° 27' 46.93538"; Longitude: West 123° 45' 42.83662".</p>		
<b>Sketch of Found Monument:</b>	<b>Sketch of Set Reference Monuments:</b>	
<p><b>New accessories set:</b> Set a 72" hat section post North 61.7'.</p> <p>Set a 2" diameter Tillamook County Brass Cap in concrete as a reference monument to the found section corner brass cap. This 2" diameter brass cap bears South 83° 04' 13" East 41.67'. Latitude: North 45° 27' 46.88574"; Longitude: West 123° 45' 42.25622".</p> <p>Set a 2" diameter Tillamook County Brass Cap in concrete as a reference monument to the found section corner brass cap. This 2" diameter brass cap bears North 20° 06' 40" East 31.14'. Latitude: North 45° 27' 47.22414"; Longitude: West 123° 45' 42.68635".</p> <p>Grid bearings have been converted to field bearings by applying a counter-clockwise rotation of the convergence angle of 2°18'47" to the grid bearings.</p>		
<b>Bearing Trees:</b> No new bearing trees were marked for this corner.		
<b>Location &amp; Comments:</b> This corner monument is located in a grassy area between a driveway and the Old Wilson River Highway at a sharp curve in the road.		
<p><b>Firm / Agency:</b>  <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE                  201 Laurel Avenue                  Tillamook, Oregon 97141</p>		<b>SURVEYOR'S SEAL</b>
<p><b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Deputy County Surveyor and Survey Supervisor.</p>		
<p><b>Notes:</b> Digital images have been taken of the found corner monument and the two reference monuments.</p>		<p>RENEWAL DATE: 08-30-2013</p>
<p><b>Witness:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor; Michael R. Rice, P.L.S. 86926, Survey Technician.</p>		