

T4R10W T4NR9W  
 36 31  
 1 6  
 T3NR10W T3NR9W

TILLAMOOK COUNTY REWITNESS # 108  
 SEC. 36 | 31  
 TOWNSHIP COR. 1 | 6 T 4 | 3 N R 9 | 10W., WM.

T3NR9W Pg 13  
 HISTORICAL: GLO T3NR10W Pages 5 & 79


MAP B-584	C-373
Book 4 Pg 88	
Book 1 Pg 95	

CONDITION Good FOUND: 1" Iron Pipe Book 4 Page 88

NOT FOUND	12" Hem S80°E	4 <sup>1/2</sup> ' =	GLO Pg 5479
NOT FOUND	14" Hem S66°W	69 <sup>1/2</sup> ' =	GLO Pg 5479
NOT FOUND	12" Spr N55°E	68 <sup>1/2</sup> ' =	GLO Pg 5479
NOT FOUND	30" Hem N55°W	42 <sup>1/2</sup> ' =	GLO Pg 5479
Now <sup>40'</sup> Stump	36" Hem S37°W	23 <sup>1/2</sup> ' ft	Book 4 Pg 88
Now <sup>30'</sup> Stump	18" Hem S30°E	67 <sup>1/2</sup> ' ft	Bk 4 Pg 88
Standing head face	24" Spr N60°W	37 <sup>1/2</sup> ' ft	Bk 4 Pg 88
COMMENTS: Fallen Stump SCRIBING VISIBLE 2'20" HIGH	14" Spr N 0° E	103 <sup>1/2</sup> ' ft	Bk 4 Pg 88

REWITNESS

1 SET 2" Iron Pipe with 3" Brass Cap in 10" Tile and concrete over found 1" I.P.



\* 96" Hat Section South 15'

NEW ACCESSORY: 3-31-80 IN HEAVIER PEN

* 12" HEMLOCK	S. 24° W 16 <sup>06</sup> '	S1 BT
* 6" HEMLOCK	N. 16° E 84 <sup>30</sup> '	S31 BT C6
FD. 20" HEMLOCK	S. 54° E 31 <sup>9</sup> '	FACED HEALED CORNER

COMMENTS: (Found in field) Scriming was visible on all b.t.s that are mentioned in Book 4 Pg 88.

THIS CORNER IS LOCATED 1,500 FT. NORTH OF THE POWER LINES & 1,500' WEST OF THE SAME POWER LINES. & IS A POINT ON THE

NORTH LINE OF RIVER BEND #1 SUBDIVISION IN THE PRESENCE OF: Geo W Urvey  
 CS MAP # 373 2° E Gale Arthur AD 3-31-80

DATE: July 1972 PHOTO # N-11-95

\* - County corner tag affixed.

TILLAMOOK COUNTY REWITNESS TITLE