

3	2
10	11

TILLAMOOK COUNTY REWITNESS # 582

SEC. COR. 3 | 2
10 | 11 T 3 S R 10 W., WM.

HISTORICAL: GLO BK 3 S 10 pg 23
BK 2 pg 497
 Maps A-1008
A-1475
B-833

CONDITION	FOUND:	SEC. COR.
Fd Good	1 1/4" galvanized pipe with lead plug stamped T3S R10W	<u>3 2</u> <u>10 11</u>
Fd (GLO)	10" Dia Fir stump 1/2' High N 52 W 4.6' No MKS Visible	
	gone all other GLO BTs. and Collards NW & SW BTs.	
Fd (BK2 pg 497)	10" Alder with rotted face N 50 E 10.2' No MKS Visible	
Fd (" " " ")	36" Douglas Fir stump S 33 E 59.8' No MKS VISIBLE	
Fd good	ALL New BTs As reported on Map B-833	

COMMENTS:

REWITNESS

1 SET A 1 1/2" x 30" IRON PIPE with a BRASS CAP
 in a form filled with CONCRETE.
 Hat Section Corner tag on 4"x4" white post

T3S R10W
53 | 52
510 | 511
 R5793
 1981

NEW ACCESSORY: 1 ft south

None		

COMMENTS: The corner lies ± 30 ft East of Dead End logging Road. I replaced Collards IP and lead plug with a CSBC, and layed said IP + lead plug alongside.

IN THE PRESENCE OF: TERRY JONES
GALE ARTHUR

DATE: Aug 1981 PHOTO#: SEC 1014 TITLE

* = County corner tag affixed.