

TILLAMOOK COUNTY, REWITNESS #758

DVLE: 18  
19

1/4 S. 18

N. 1/4 1010 SEC. 18  
COR. 19 T 4S R 10 W., WM.

HISTORICAL: GLO Pg 48 4510 + 1879

BOOK	PAGE	BOOK	PAGE	MAPS	A-188
4	32	P4	6-12	A-353	
4	104	P9	143	A-1055	
53	18	10	7	B-535	
40	5	53	18	F25-36	

CONDITION FOUND: 2" IRON PIPE WITH WHITE LOT STAKE BK4 Pg 104

CONDITION	FOUND	BEARING	DISTANCE	REFERENCE
GONE	24" FIR	N 13° W	113 LKS	GLO Pg 48
GONE	5" ALDER	S 40° W	120 LKS	GLO Pg 48
GONE	28" SPRUCE	S 67° E	185 LKS	BK 10 Pg 7
GONE	48" DEAD SPRUCE	S 80° W	48 LKS	BK 10 Pg 7
GONE	6" ALDER	S 40° E	22 1/2 FT	BK 4 Pg 32
*FD SCRIBING VISIBLE	10" SPRUCE	S 70° W	12 1/2 FT	BK 4 Pg 32 <small>Now 30' SW 6-8-82</small>
*FD SCRIBING VISIBLE	8" SPRUCE	N 30° E	49 FT	BK 4 Pg 104
*FD SCRIBING VISIBLE	10" ALDER	S 62° 30' E	44 25 FT	BK 4 Pg 104

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE AND CEMENT IN POSITION OF FD 2" IRON PIPE

4" Hat Section ~~15 FEET~~ ~~12 FEET~~ Now N. 42° W D1 P 12-88

NEW ACCESSORY:

NEW ACCESSORY	BEARING	DISTANCE	REFERENCE
40" SPRUCE	S 22° W	17 1/2	1/4 S 19 BT CS

1973

COMMENTS: THIS CORNER IS LOCATED ± 50' EAST OF SANDLAKE WOODS ROAD ON A BRUSHY HILLSIDE.

IN THE PRESENCE OF: GALE ARTHUR, DAN McNUTT,

DATE: 11-73 PHOTO: 2EC

County corner tag affixed.