

TILLAMOOK COUNTY REWITNESS **779**  
 N. 33 SEC. 28  
 COR. 33 T 4S R 10 W., WM.

S. 28  
 HISTORICAL: GLO PG. 34 4510 SET SPRUCE POST 1879  

BOOK	PAGE	MAPS
10	103	B-118
53	466	


SEE MISC. SEC. FILE S. 28 T4S R10 W FOR FIELD NOTES  
 OF TRAVERSE BASED ON CS MAP "B-118" DATA.

CONDITION	FOUND:	NOTHING AT CORNER POSITION
FD REMAINS OF UPROOTED ALDER	9" ALDER	N. 80° E. 12 LKS GLO Pg 34
FD REMAINS OF UPROOTED SPRUCE	3 1/4" SPRUCE	S. 20° W. 26 LKS GLO Pg 34

COMMENTS: THIS CORNER IS LOCATED IN A SWAMPY AREA  
 ± 50 WEST OF A CREEK & ± 75' EAST  
 OF AN OLD GROWN OVER ROAD.

REWITNESS

I SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE &  
CEMENT FROM TIES ON CS MAP B-118  
 84" Hat Section NORTH 15 FEET



NEW ACCESSORY:

12" ALDER	N. 5° E. 24 7/8'	1/4 528 CS BT
12" ALDER	S. 60° W. 70 1/2'	1/4 533 CS BT

COMMENTS: THIS CORNER WAS POSITIONED FROM FD.  
 1/16 CORNERS ON THE E OF THE NW 1/4 OF S. 33. AS THE BEARINGS &  
 DISTANCES ON CS MAP B-118 WOULD NOT CLOSE BY ± 70' EAST. THE TIE  
 FROM THE N 1/16 OF S. 33 WAS USED RATHER THAN THE CN 1/16. A CHAINING  
 FACTOR WAS DETERMINED FROM FD 1/16  
 IN THE PRESENCE OF: ALONG THE E OF S. 33 4510.  
 THEN W 1/4

GALE ARTHUR DAN MCNUTT

DATE: 1-7-80 PHOTO#: 114180 J. L. Carlin Co. Surveyor  
 TITLE

\* = County corner tag affixed.