

## T 2 N R 10W Section 25/36 Quarter Corner Reset.

On the basis of the Affadavit of Harold S. Williams, duly notarized and recorded in Book Of Deeds, Book 130 page 99 the original of which is attached hereto, in which Williams marks a point which he states is within 5 feet or less of the true position of the original corner, at the point he showed me, I drive an Automobile Drive Shaft, with gear attached, 5 feet long, flush in ground, and make new Bearing trees:

Spruce 14" bears South 20.0 feet.

Hemlock 24" " N 14° W 48.7 feet

Both trees scribed on bark "1/4 S 25 (36) B T 1842" and in each tree a large head Aluminum nail to mark the point of measurement.

Done Nov. 8, 1952.

W A Markham  
Registered Engr. #1842

Rewitness June 1972

Geo W Urrey

Gale Arthur

Tim Boehm

I removed the above axle with gear set by WAM. and placed a Brass Cap in Concrete At position of fd axle with gear.

Book I

186