CHAINS

CORRECTION REPORT

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 2, 3, 10 and 11, T6S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

No evidence of original corner found.

Uncovered a 74 year old line blaze S89°23'E at 129.7 ft. and an original at 849.1 ft. Other originals were found in the same vicinity on the same line, as well as more recent blazes.

Uncovered an original line blaze S0°43'E 1175.9 ft. County Corner bears N 1° 02' 12" E 1144.1 ft.

More recent line blazes of different ages were found both North and West of the intersection (see below).

RESTORATION by unknown party, notes recorded in County Surveyor's office 1887. No evidence of restoration found.

RESTORED

Var. 201E

At intersection of original blazed lines (see above), set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T6S R9W S2 S3 S10 S11 1962 RS 559", 26 inches in ground, in notched out down log, and from which a:

66" Fir stump bears N25E 65.1 ft.; scribed T6S R9W S2 BT.

21" Hem. bears S492E 19.8 ft.; scribed T6S R9W S11 BT RS 559.

24" Hem. bears N68W 27.6 ft.; scribed T6S R9W S3 BT.

27" Hem. bears $538\frac{1}{2}$ W 27.9 ft.; scribed T6S R9W S10 BT.

Oregon State Forestry Department metal location poster on 21" Hem. BT. Set 4" x 72" white painted Cedar post 1.0 ft. W of corner pipe.

Dated April 15, 1963

Restored by

Present and witnessed by Dave Steenson
John Hollingsworth
Ron Schulson

REGISTERED
OREGON
LAND SURVEYOR
Elbut Striver

JANUARY 12, 1962 Elbert Driver 559

426

456

Book I