

SEE PG 95

Sec 27-28-33-34, T. 4. S. R. 10 W. W.

1" I.P. edge of Highway 101
10" Tripple Walnut 54° E 35.8
10" " " N 85° 30' E 94.6 GONE

NOT CORRECT
1949 W.E. Anderson Jr

1/4 Cor between 19-20 T. 4. S. R. 10 W. W.

2" I.P. Badly Rusted

34" spruce 51° 22' W 11.66

8" Alder old B.T. 53° E 22.5

1/4 18/19

June 30, 1949

W.E. Anderson Jr

Sec 28-29-32-33 T. 4. S. R. 10 W

found old spruce limb on fence line

E & West Mark Visible


Set 1" gal pipe made (mound?) (rock?) around of rod.

See Book P 83 for same of Center

W.E. Anderson Jr

Aug-15, 1949

8x8 post Navy fence.



1/4 Cor set 1" I.P. 4'

between sec 9 & 16 T. 2. S. R. 9 W

W.E. Anderson Jr

S 1/6 E 64y


* X NE Cor of SE 1/4 of SE 1/4 of Sec 9

T. 2. S. R. 9 W.

3" I.P.

5x5" Concrete Monument

1949 W.E. Anderson Jr. & Jr.



* Sec cor 9-10 16-15

T. 2. S. R. 9. W. W. M.

1949 W.E. Anderson Jr. & Jr.

Re witness Sec. Cor

Set 2" Iron pipe

T. 1. S. R. 9-10. W.

Oct-1949 W.E. Anderson Jr. & Jr.

Found 4" Hemlock N 41° W 19 lbs

" 34" Hemlock S 22° W 9 lbs

Badly decayed. But marks visible

Made 18" Alder = S 74° 30' W - - 27.3 feet

" 12" Spruce = N 22° W - - 31.6 feet