

Oregon State Parks and Recreation Division Survey  
Nehalem Bay State Park  
NE¼ Section 32, T3N, R10W, W.M.  
Tillamook County, Oregon  
September 26, 1983

NARRATIVE  
(See Accompanying Plat)

The purpose of this survey was to establish the boundary of Nehalem Bay State Park located in the NE¼, NE¼ Section 32, T3N, R10W, W.M.

Control was established using a Jena one-minute theodolite and a McHenry "Mac II-H" electronic distance measuring instrument.

The bearing basis was from an Oregon State Highway Department plat, County Survey No. B-514, dated January 1963 and stamped by John A. Bond, resident engineer. The bearings are "Grid", north zone, and the theta angle is 2026'13".

Corner Information  
Var. 21½°

Section Corner 28, 29, 32, and 33

Tillamook County Rewitness December 1971:

Found 2" iron pipe with brass cap still in position.

Brass cap marked "T3NR10W-S29,S28,S32,S33-RS 793-1969".

Hat Section North 1.5 ft.

Found remains of bearing trees - all bearing trees referred to in book 10 page 83 are gone - all G.L.O. bearing trees of 1857 are gone. New accessory 16" pine N70°E - 54.55 to face of scribe "S28BTCS" (Now 18").

Parks Crew Found:

Brass cap as per county notes.

Metal post was found lying down.

18" pine N82°E - 55.5 feet to center with Tillamook County corner tag and scribes "S28BTCS".

12" spruce (dead) N20°W - 157.7 feet to center with Tillamook County corner tag and grown over blaze.

Set 7' plain fiberglass post 2.0 feet north of brass cap.

Witnessed by: A. Slack  
R. LeTourneux  
D. Polly

Quarter Corner Between Sections 29 and 32

Tillamook County Rewitness August 1974:

Set 2" iron pipe with 3" brass cap marked "¼ S29,S32,RS287-1974" in 10" tile and cement over found 1½" iron pipe.

Found hat section east - 24.5 feet with county corner tag.

Corner is located + 14' east of the centerline of road and + 6' east of east edge of pavement on Necarney City Co. Road. Corner is now + 4" deep in the intersection of Lakeview Drive and Necarney City Co. Road.