

TILLAMOOK COUNTY SURVEYORS OFFICE
COURT HOUSE, TILLAMOOK, OREGON 97141

S1/16 CORNER COMMON SECTIONS 28 & 29 T.2S., R.9W., W.M.

T2SR9W
1/16 I found a 1" iron pipe approximately 4" below the
| road surface, (See T.C.S. map #B-404 for establish-
S29+S28 ment). I set a 5/8"X 12" iron rod with a 3" Tillamook
| County Surveyor Brass Cap in an 8" cast iron
RS 793 monument case and concrete from references after road
1990 was reconstructed.

History of found monument

I found This monument to be as described on T.C.S. Map #A-404 and the Set at that time to now be as follows:

3" bronze disk B.M. V+48 S.3 1/2*W. 130.7'; (Now gone, destroyed by road construction).

27" cedar S.72*W. 43.1'; (Now gone, destroyed by road construction).

New Accessories

5/8" iron rod with a Red Tillamook County Surveyors Plastic Cap inscribed "TILLAMOOK CO. SURVEY" N.35*25'06"W. 62.64'.

5/8" iron rod with a Red Tillamook County Surveyors Plastic Cap inscribed "TILLAMOOK CO. SURVEY" S.64*44'06"E. 69.79'.

5/8" iron rod with a Red Tillamook County Surveyors Plastic Cap inscribed "TILLAMOOK CO. SURVEY" N.51*E. 86.80'.

5/8" iron rod with a Red Tillamook County Surveyors Plastic Cap inscribed "TILLAMOOK CO. SURVEY" S.51*W. 47.64'.

Basis of Meridian is a magnetic compass. Angles were turned with a Wild T-16. Distances were measured with a Wild "DI 5" E.D.M.

*84" light hat section post West 36.0'.

*indicates Tillamook County Surveyors yellow metal location poster attached.

Surveys and Rewitnesses of Record

A-1924	May -70	John L. Carlich	RS 287
A-2211	Nov. -71	John L. Carlich	RS 287
A-2490	Nov. -73	John L. Carlich	RS 287
A-4181	Sum. -77	John L. Carlich	RS 287
A-4324	09-20-78	John L. Carlich	RS 287
A-3452	Apr. -78	John L. Carlich	RS 287
B-404	Mar. -59	Richard A. Morris	RS 401
A-792	June -59	Richard A. Morris	RS 401
Rewitness Book 1 Page 383	Apr. -59	Richard A. Morris	RS 401
A-3817	June -79	Frederick Gaylord	LS 929
B-821	Jan. -79	C. Wayne Cook	LS 1098
A-4637	Dec. -81	C. Wayne Cook	LS 1098
B-1512	04-08-91	Charles D. Curtis	LS 2274
F-27-30	1972	O.S.H.D.	


Location of Monument

This corner is located in the approximate center of the South bound lane of Highway 101.

In the presence of Al Dvorak and Dan McNutt

December 18, 1990

Title



Allan E. Duncan, C.S.

