

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

**BOOK 8 212**

<b>SECTION:</b> 29 and 28	<b>TOWNSHIP:</b> 1 South	<b>RANGE:</b> 10 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b>
<b>CORNER DESIGNATION:</b>		<b>(Please check one)</b>
The Quarter Corner common to Sections 28 and 29, Township 1 South, Range 10 West, Willamette Meridian; Tillamook County, Oregon.		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out

**Previous Rewitnesses, Restorations and Surveys, etc...**  
Map B-3635 (2014)

**History, condition, and sources**

In 2014 (Map B-3635) Terry Jones PLS 2507 Set a 1" galvanized iron pipe with a 2 1/2" brass cap stamped "1/4 S29 S28 LS 2507 2014". The position was established by single proportion between the found NE corner of Section 29 and the SE corner of Section 29 from which he established 4 new accessories. In 2024 (Field Book MR 17 pg. 25-28 12/2024) the Tillamook County Surveyors Office Found a 2 1/2" brass cap stamp as shown hereon to be in good condition. The references are Listed below.

**Found:** (Map B-3635) steel post South 1' **now** with metal location tag.

**Found:** (Map B-3635) 12" dia. fir North 1.5' no scribing or metal location tag **now** 13" dia. N 19° W 1.7' to face of tree.

**Found:** (Map B-3635) 12" dia. fir N 64° W 10.43' scribed "1/4 S29 BT **now** 15" dia. 10.2' to face of tree with healed scar and metal location tag.


**Found:** (Map B-3635) 14" dia. hemlock S 08°55' E 9.89' scribed "1/4 S28 BT" **now** 17" dia. 9.9' to face of tree with healed scar and metal location tag.

**New accessories set:**

The Monument was tied directly using GPS in Oregon North Zone NAD 83/91 grid coordinates in US Survey feet. Coordinates provided hereon are given in WGS 84 Latitude and Longitude.

Latitude: 45°27'24.42450"  
Longitude: -123°55'39.40690"

No new bearing tress available.



**Pictures of Found Monuments:**



**Location:** ± 200' West of logging road #611


**Tillamook County Surveyor office:** 1510 3<sup>rd</sup> Street Suite C, Tillamook, OR. 97141

**Party Chief:** Travis Porter, Tillamook County Surveyors Office


**Witnesses:** Michael Rice P.L.S. 86926, Tillamook County Surveyor  
Kael Poklikuha, Tillamook County Survey Technician

**Notes:** Digital images taken of monument and accessories.

**SURVEYOR'S SEAL**



*Michael R. Rice*



RENEWAL 12-31-2026

**BOOK 8 212**