

TILLAMOOK COUNTY REWITNESS # 197
 Section COR. ~~16~~ 15 16 15 21 22 T 15 R 9 W., WM.


HISTORICAL: GLO-1857 - Page 58 - H. MELDRUM
 Book 1 Page 47 - WE Anderson / F. L. Smith Dec. 1960
 Book 4 Page 98
 Book 4 Page 16 - 1905 - Jacobs & Davis
 MAP A-700 - J. L. Carlsh - 1957 - Subdivision Sec 22
 MAP A-1099 - RAMORRIS - 1963 - Subdivision Sec 16

CONDITION	FOUND:
Dying (o.k. 1972)	2" Iron Pipe at ± 40 inches below ground
Fallen over (Gone 1972)	Willow 6" East 58' S 22 BT } REFER TO BK 4 P 98
	Willow 6" N 32° E 850 S 15 BT }

COMMENTS: OSBF (1963) Tag on 6" Willow East 58' of corner

REWITNESS

1 SET 2" Iron Pipe over old pipe -- making pipe now 12" above ground
 Scribed 4" x 4" x 48" Post N. 1/2 E. Hat Section 1/2 E.



NEW ACCESSORY:	Scribed
12" Alder GONE	S 35° E 1885 S 22 BT CS
12" Alder GONE	S 01° E 1925 S 22 BT CS
6" Willow GONE	N 32° E 1160 S 15 BT CS
10" Tile Filled with Concrete	

COMMENTS: No tags set at this date 6/1/65

IN THE PRESENCE OF: S S Skinner
 Gale Arthur

DATE: 6-1-65

PHOTO#: 210

* = County corner tag affixed.

TITLE
 G.W.