


TILLAMOOK COUNTY REWITNESS

#385



NW 1/6 COR.

SEC.

10 T 25 R 9 W., WM.

DIC. #

Reproduced W.E. Anderson's survey of

HISTORICAL: Rosenberg Tracts, 1948 -- Refer to MAP A-293

Bk. 35 Page 78 HAYES 1896 Survey for H. Lederer found 1/6 Stake Marked C.S.

Bk. 35 Page 162 HAYES 1898 Survey Road Change of Brickyard Rd

MAP F-17-5 W.S. Coates 1929 County MARKET Road #14

MAP F-9-2 W.E. Anderson 1933 Long Prairie Water District

MAP A-427 W.E. Anderson 1950 Survey J.H. Rosenberg Tract

MAP A-1685 J.L. Carlich 1969 Survey for Hugo Stelzig


CONDITION

FOUND: 60 D Spike at reproduced position

COMMENTS:

REWITNESS

1 SET 1 1/4" Iron Rebar with Brass Cap



* 06 Hat Section S. E. South 58° East

feet 22.0

NEW ACCESSORY:

Power Pole 16 P29-130 WEST 29.35

Power Pole 1 P29-130R1 N70°E 56.55

COMMENTS: Corner is located EAST of apparent centerline of Brickyard Road. Corner is located South of apparent centerline of Mills Creek Road.

IN THE PRESENCE OF: Gale Arthur
George Urrey
AL Duncan

DATE: 7-15-70

PHOTO: REC

County corner top affixed.

TILLAMOOK COUNTY REWITNESS

TITLE GWU