

DYLE  
 2 2  
 2 7

TILLAMOOK COUNTY REWITNESS

117E 1039

HOLO. SEC. 22  
 1/4 COR. 27 T 45 R 10 W., WM.

HISTORICAL: GLO Pg 28 4510

F	BOOK	PAGE	AMA
40-91			9 45
B-31	10	66 <sup>1888</sup>	1-31
A-72	10	127 <sup>1888</sup>	
A-999	53	40 <sup>1875</sup>	
	53	290 <sup>1875</sup>	


B-1449

CONDITION	CORNER POINT	MISSING	
GONE	3 1/2" WILLOW	N 56 W	8 LKS GLO. Pg 28
GONE	4" WILLOW	S 2 E	25 LKS GLO. Pg 28
GONE	72" SPRUCE	N 31 W	71 LKS BK10 Pg 66
SAME AS ORIGINAL!	GONE	WILLOW	S 5 W 25 LKS DK10 Pg 66

COMMENTS:

REWITNESS

1 SET 2" IRON PIPE WITH 3" T.C.S. BRASS CAP IN TILE & CONC.



N.W. feet  
 S. E.

NEW ACCESSORY:


COMMENTS: THIS CORNER WAS SET FROM  
 TIES SHOWN ON MAP B-31. T.P.S FOUND ON NLY  
 SIDE OF 20' LANE.

IN THE PRESENCE OF: A. DUNCAN  
 GALE ARTHUR

DATE: 6-12-72 PHOTO: REC

\* - County corner tag affixed.