

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 14 and 23, Township
1 South, Range 9 West, W.M., Tillamook County, Oregon. (e. Side)

ORIGINAL

Post, now missing, (3/4" g.i.p. in place), from which a:

- 36" Hemlock bears S34°W 17 lks.; now 36" rotted stub 6 ft. high, portion of B scribe remaining.
- 15" Hemlock bears N17°W 22 lks.; now missing, root hole in place.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R9W S14 S23 1954 RE 2311," 24 inches in ground, over top of 3/4" g.i.p., and from which a:

- 20" Fir bears S72°W 74.8 ft.; scribed T1S R9W S23 BT.
- 24" Spruce bears N69°W 49.0 ft.; scribed T1S R9W S14 BT RE 2311.

Oregon State Board of Forestry metal location poster on 24" Spruce BT.
Also poster on 8" Fir on ridge North 292.2 ft.
Also poster on 12" Spruce West 108.1 ft.

Dated August 11, 1954.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Asst. Engr.



Present and witnessed by Forest Logan