

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 15 and 22,
Township 3 North, Range 6 West, W.M., Tillamook
County, Oregon.

ORIGINAL

Post, now missing, (1" x 4" pipe in place) from which a:

- 30" Hemlock bears N13½°W 6 lks.; now 24" stub
4 ft. high, BT. scribes remaining.
- 9" Hemlock bears S49½°W 49 lks.; now missing,
roots in place.

RESTORED

Erected stone around pipe from which a:

- 6" Fir bears N60°E 15.8 ft.; scribed 1/4 S15 BT.
- 8" Fir bears S 5°E 53.0 ft.; scribed 1/4 S22 BT
RE 2311.

Oregon State Board of Forestry metal location poster on
6" Fir BT.

- Also poster on 48" Hemlock snag S68°E 21 ft.
- Also poster on 3" dead Fir S51°E 23 ft.
- Also poster on 4" x 4" x 36" post on North edge
firebreak road 2376 ft. East of corner.
- 4" x 4" x 72" white Cedar post 1 ft. SW of pipe.

Dated April 15, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan
Lloyd Geraths