

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 22 and 23,
Township 3 North, Range 6 West, W.M., Tillamook
County, Oregon.

ORIGINAL

Post, now rotted point in place, possibly original,
from which a:

- 16" Hemlock bears N68 $\frac{1}{2}$ °E 47.5 lks.; now 24" stub 20 ft. high, part of BT scribes visible, upper face unexposed.
- 36" Fir bears N81 $\frac{1}{2}$ °W 6 lks.; now 40" stump, face grown over.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S22 S23 1954 RE 2311," 32 inches in ground, in mound of stone, and from which a:

- 6" Fir bears N88°E 24.3 ft.; scribed 1/4 S23 BT.
- 7" Fir bears N22°W 37.2 ft.; scribed 1/4 S22 BT RE 2311.

Oregon State Board of Forestry metal location poster on original 16" Hemlock BT.
Also poster on 6" Fir BT.
4" x 4" x 86" white Cedar post lft. NE of pipe.
Also poster on 7" Fir on East bank R.R. grade 198 ft. West of corner.

Dated April 15, 1954.

Restored by *Richard Morris* under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan
Lloyd Geraths

Book I