

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 15, 16, 21 and 22 Township 1 North, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 8" Hemlock bears N54°W 9 lks.;
now 12" burned out stump. 4 ft. high.
- 8" Hemlock bears N47°E 37 lks.;
now 8" stub 3 ft. high, face burned off.
- 9" Hemlock bears S61°E 29 lks.;
now 12" stub 3 ft. high, BT scribes visible.
- 5" Hemlock bears S53°W 40 lks.;
now just roots remaining under log.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R7W S15 S16 S21 S22 1953 2311," 30 inches in ground, in small mound of stone, and from which a:

- 47" Fir stump bears N51½°W 31.5 ft.;
scribed T1N R7W S16 BT.
- 52" Fir stump bears N75°E 13.2 ft.;
scribed T1N R7W S15 BT.
- 39" Fir stump bears S80°W 15.0 ft.;
scribed T1N R7W S21 BT.
- 42" Fir stump bears S12°E 11.6 ft.;
scribed T1N R7W S22 BT RE 2311.

Oregon State Board of Forestry metal location poster on 52" Fir stump BT.
Also poster on 4" x 4" x 50" Cedar post on East bank Archer Road 530.7 ft. East of corner.
Set 4" x 4" x 72" White Cedar post 3 ft. Southeast of corner pipe.

Dated December 18, 1953.

Restored by *Richard Morris* under my direction. Richard Morris, Compassman



Present and witnessed by Lloyd Geraths
Alan Ramage