

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 23, 24, 25 and 26
Township 1 South, Range 7 West, W.M., Tillamook
County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears S52°E 77 lks.; now missing
this tree used in 1952 restoration below.
Scribes then visible.
- 8" Hemlock bears N56°E 12 lks.; now missing.
- 6" Hemlock bears N30°W 44 lks.; now missing.
- 10" Hemlock bears S31°W 7 lks.; now missing.

RESTORATION by L. W. Amort, June 7, 1952

1½" x 36" galvanized iron pipe with cap marked as
below, now misplaced by logging, from which a:

- 9" Alder bears S42°E 83.7 ft.; now missing
point falls in skid road.
- 17" Maple bears S46½°W 16.1 ft.; now uprooted
and out of place, no evidence of original
position, scribes WC T1S R7W S23 BT
RE 2311.
- 5" Alder bears N67½°W 12.3 ft.; now 6" stub
cut off at ground level, butt piece with
scribes WCX BT brought in for preservation.
- 52" Fir snag bears N10½°E 21.0 ft.; now 50"
stump, scribes 2311 remaining.

RESTORED


Set 1½" x 36" galvanized iron pipe with 3" bronze cap
(see above Restoration) marked "OREGON STATE BOARD OF
FORESTRY WC T1S R7W S23 S24 S26 S25 125 lks. S 1952
2311," 33 inches in ground, in mound of stone 6'x4'x18",
and from which a:

- 43" Fir stump bears N33½°W 65.6 ft.; scribed
WC T1S R7W S23 BT RE 2311.
- 52" Fir stump bears N51°E 75.3 ft.; scribed
WC T1S R7W S24 BT.
- 50" Fir stump bears S64°E 144.5 ft.; scribed
WC T1S R7W S25 BT.

Oregon State Board of Forestry metal location poster on 43"
Fir stump BT.
Also poster on 4" x 4" x 60" white Cedar post 2 ft. NE of
pipe.

Dated March 23, 1954.

Restored by *Richard Morris* under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan, Alan Ramage, Lloyd Geraths