

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to sections 14 and 23,
Township 1 South, Range 7 West, W.M., Tilla-
mook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 20" Hemlock bears S64¹/₂°W 39 lks.; now 30" stub 20 ft.
high, scribes S B visible, rest unexposed.
- 18" Hemlock bears N34°E 30 lks.; now 19" stub 6 ft.
high, scribes 1/4 S BT visible.

RESTORED


Set 1¹/₂" x 36" galvanized iron pipe with 3" bronze cap m
marked "OREGON STATE BOARD OF FORESTRY 1/4 S14 S23
1954 RE 2311," 28 inches in ground, in mound of Stone
5' x 4' x 10", and from which a:

- 54" Cedar snag bears N20¹/₂°E 21.7 ft.; scribed 1/4
S14 BT RE 2311.
- 58" Cedar snag bears S64°W 31.0 ft.; scribed 1/4
S23 BT.

Oregon State Board of Forestry metal location poster on
54" Cedar snag BT.
4" x 4" x 60" white Cedar post 1.5 ft. SE of pipe.

Dated March 23, 1954

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Lloyd Geraths, Robert Cowan