CHAINS

Restored Corner for Oregon State Board of Forestry

One quarter corner common to Sections 23 and 24 Township 2 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL:

Post, now missing, from which a:

48" Larch bears N&IE 56 lks.; now 63" stub 25 ft. high, 4S BT scribes visible.

52" Larch bears S35W 28 1ks.; now 52" stub 45 ft. high, BT scribes visible.

RESTORED:

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked (OREGON STATE BOARD OF FORESTRY 1/4 S23 S24 1954 RE 2311," 34" in ground, in mound of stone, from which a:

41" Fir snag bears N12E 121.3 ft.; scribed 1/4 S24 BT RE2311.

34" Fir stump bears S4W 121.7 ft.; scribed 1/4 S23 BT.

Oregon State Board of Forestry metal location poster on 34" BT stump on South edge ridge road. Set 4" x 4" x 72" white Cedar post 1.5 ft. SE of pipe. Also poster on 36" Hemlock on North edge firebreak road #8 S24E 54 ft.

Dated September 21, 1954.

Restored by

Richard Morris, Engr. Aide

under my direction

iow am

Present and witnessed by Lloyd Geraths Robert Schumacher Robert Reutlinger

Book I