

139 139

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 4,5,8 and 9, T1S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 6" Hemlock bears N37°W 40 lks.; now 1 ft. high rotted stub.
- 6" Hemlock bears N51°E 20 lks.; now 18" by 6 ft. high stub, T1S scribes exposed.
- 7" Hemlock bears S31°E 73 lks.; now 18", down, face burnt out, original axe marks remaining on edges.
- 5" Hemlock bears S50°W 26 lks.; now 12", down, T1S scribes remaining.

RESTORATION by Garth M. Cross, March 31, 1951.

Post, now out of place, from which a:

- 4" Alder bears S72°E 53 lks.; now 8", CS T1S R8W S9 BT RS.259 scribes visible in bark, but tree now bears S66°E 32.8 ft.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R8W S4 S5 S8 S9 1954 RE. 2311," 24 inches in ground, and from which a:

- 6" Fir bears N79½°W 42.1 ft.; scribed T1S R8W S5 BT.
- 84" Double Fir snag bears S10½°E 35.9 ft.; scribed T1S R8W S9 BT RE 2311.
- 54" Fir stump bears N46½°E 136.6 ft.; scribed T1S R8W S4 BT.

Oregon State Board of Forestry metal location poster on 6" Fir BT.

Set 3"x4"x80" white Cedar post 1 ft. SW of pipe.

Dated November 26, 1954.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Ass't. Engr.



Present and witnessed by Richard Morris, Forest Logan
Claude Weikel