

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 8,9,16 and 17, T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

18"x10"x8" basalt stone, now in place, under East side of log 53"x13", 4 Notches on S side and 4 on E side, from which a:

- 12" Hemlock bears N36°E 17 lks.; now just roots remaining.
- 12" Hemlock bears S52°E 19 lks.; now just roots remaining.
- 48" Fir bears S10°W 17 lks.; now 52" stump, BT scribes remaining.
- 14" Hemlock bears N50°W 50 lks.; now 22" stub 15 ft. high burnt face remaining.

RESTORED

Erected mound of rock around East side of corner stone from which:

- 43" Fir stump bears S51°W 85.4 ft.; scribed T2N R8W S17 BT RE 2311.
- 54" Fir stump bears S50°E 87.8 ft.; scribed T2N R8W S16 BT.
- 66" Fir stump bears N54°W 46.2 ft.; scribed T2N R8W S8 BT.
- 39" Fir stump bears N26°E 59.0 ft.; scribed T2N R8W S9 BT.

- Oregon State Board of Forestry metal location poster on 39" Fir stump BT.
- Oregon State Board of Forestry metal location poster on original 48" Fir BT.
- Oregon State Board of Forestry metal location poster on 24" Fir stub 580 ft. East on South edge log road.
- Set 4"x4"x84" white Cedar post 2 ft. SE of corner stone.

Dated December 8, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. aide



Present and witnessed by Claude Weikel  
Forest Logan  
Lloyd Geraths