

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 15 and 16, T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

13"x9"x6" stone, now missing, point covered by land slide, from which a :

18" Hemlock bears N36°W 22 lks.; now 20" stub 30 ft. high, portion of S and BT scribes visible.

24" Hemlock bears S44°E 45 lks.; now 24" stub 10 ft. high, edge of burnt face visible.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY ¼ S15 S16 1954 RE 2311," 36 inches in ground, in mound of stone, and from which a:

66" Fir stump bears N84°W 47.9 ft.; scribed ¼ S16 BT.

66" Fir stump bears N55°E 46.7 ft.; scribed ¼ S15 BT RE 2311.

Oregon State Board of Forestry metal location poster on original 18" Hemlock BT.

Oregon State Board of Forestry metal location poster on 66" Fir stump BT N84°W.

Set 4"x4"x84" white Cedar post 1.5 ft. NW of pipe.

Dated December 14, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Claude Weikel