

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 16, 17, 20 and 21,
T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

14"x9"x7" stone, now in place, bottom half broken off,
with 3 notches on S and 4 on E sides, from which a:

- 12" Hemlock bears N70°E 43 lks.; now 23" snag,
exposed 16 scribes.
- 8" Hemlock bears S60°E 15 lks.; now 17" uproot,
upper face burnt out, lower face unexposed.
- 14" Hemlock bears S52°W 10 lks.; now 20" uproot,
upper face burnt out, B scribe visible on
lower face.
- 12" Hemlock bears N77°W 99 lks.; now 19" uproot
out of place, root hole in place, faces unexposed.

RESTORED


Erected mound of rock around corner stone, from which a:

- 66" Fir stump bears N58°W 65.6 ft.; scribed T2N
R8W S17 BT RE 2311.
- 54" Hemlock stump bears S3½°W 96.5 ft.; scribed T2N
R8W S20 BT.
- 60" Hemlock snag bears S11½°E 11.3 ft.; scribed T2N
R8W S21 BT.

Oregon State Board of Forestry metal location poster on
66" Fir stump BT.
Oregon State Board of Forestry metal location poster on
60" Hemlock snag BT.
Oregon State Board of Forestry metal location poster on
24" Hemlock snag 135 ft. N55°E on N edge log road.
Set 4"x4"x84" white Cedar post 3 ft. SE of stone.

Dated December 14, 1954.

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Ass't. Eng.



Present and witnessed by Richard Morris and Forest Logan