

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5,6,7, and 8, T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

17"x10"x6" stone, now in place with 5 notches on S and E sides, from which a:

- 18" Hemlock bears N41°E 48 lks.; now 12" by 6 ft. rotted and burnt stub.
- 20" Hemlock bears S46°E 17 lks.; now 17" by 8 ft. rotted and burnt stub.
- 12" Hemlock bears S37°W 6 lks.; now just roots remaining in place.
- 14" Hemlock bears N20°W 45 lks.; now just roots remaining in place.

RESTORED

Erected mound of rock around corner stone, from which a:

- 50" Fir snag bears N59°E 25.7 ft.; scribed T2N R8W S5 BT.
- 4" Alder bears N6°W 13.3 ft.; scribed XBT (in bark)
- 60" Cedar stump bears S58°W 71.7 ft.; scribed T2N R8W S7 BT RE 2311.
- 4" Alder bears S23°E 9.9 ft.; scribed XBT (in bark)

Oregon State Board of Forestry metal location poster on 50" Fir snag BT.

Oregon State Board of Forestry metal location poster on 72" Fir snag approximately 250 ft. N20°W.

Set 4"x4"x84" white Cedar post 900 ft. N on S edge Cook Creek road.

Dated December 17, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Forest Logger