

## TILLAMOOK COUNTY

see page 166

replace the pipe with a 2"X 48" galv. iron pipe with brass cap on which is stamped a cross and the numbers 1-6-12-7 and, circumferentially, SEC. COR. T. 3 N. RGS. 5&6 W.W.M. - O.S.H.D. We also set a 4"X 4" white guard post stenciled SEC. COR. on 2 faces in black. No live trees available for bearing trees.

Returning to the corner to Twps. 3 and 4 N., ranges 5 and 6 W., we ran thence Westerly by traverse along the township line between sections 36 and 1.

At a point 2693.3 ft. N.  $89^{\circ} 50\frac{1}{2}'$  W. from the township corner, we found a  $1\frac{1}{2}"$  iron pin and 2 bearing trees scribed  $1/4$  S.B.T. (dead). We replace the pin with a 2"X 48" galv. iron pipe with brass cap on which is stamped a line with short cross mark and the numbers 36 and 1 and, circumferentially,  $1/4$  COR. TPS 3&4 N. R. 6 W.W.M. - O.S.H.D. We also set a 4"X 4" white guard post stenciled  $1/4$  SEC. COR. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black. No live trees available for bearing trees.

Continuing thence Westerly by traverse between sections 36 and 1 we found 2 scribed bearing trees (dead) and 1 blazed stump from which we established the corner to sections 35-36-2-1 at a point 2608.3 ft. S.  $89^{\circ} 59'$  W. of the quarter corner between sections 36 and 1.

We set a 2"X 48" galv. iron pipe with brass cap on which is stamped a cross and the numbers 35-36-2-1 and, circumferentially, SEC. COR. TPS. 3&4 N. R. 6 W.W.M. - O.S.H.D. We also set a 4"X 4" white guard post stenciled SEC. COR. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black. No live trees available for bearing trees.

Thence we ran Westerly by traverse between sections 35 and 2.

We found 2 bearing trees, both dead, for the quarter corner between sections 35 and 2 and at a point 2641.6 ft. S.  $89^{\circ} 59\frac{1}{2}'$  W. of the section corner we set a 2"X 48" galv. iron pipe for the quarter corner. This pipe has a brass cap on which is stamped a line with short cross mark and the numbers 35 and 2 and, circumferentially,  $1/4$  COR. TPS. 3&4 N. R. 6 W.W.M. O.S.H.D. We also set a 4"X 4" white guard post stenciled  $1/4$  SEC. COR. on 2 faces in black. No live trees available for bearing trees.

Continuing thence Westerly by traverse, we find all four bearing trees for the corner to sections 34-35-3-2. All bearing trees dead and 1 blown down. At a point 2619.1 ft. N.  $89^{\circ} 39'$  W. of the quarter corner we set a 2"X 48" galv. iron pipe for the corner to sections 34-35-3-2. This pipe has a brass cap on which is stamped a cross and the numbers 34-35-3-2 and, circumferentially, SEC. COR. TPS. 3&4 N. R. 6 W.W.M. - O.S.H.D. We also set a 4"X 4" white guard post with SEC. COR. stenciled on 2 faces in black. No live trees available for bearing trees.

Thence we ran Westerly by traverse between sections 34 and 3

We found a 12" hemlock scribed for a bearing tree. Placing the quarter corner from this, we find it falls in the hole of a 36" uprooted fir and that a 40" cedar stump bears S.  $45^{\circ}$  E. 25.7 ft. We set a 2"X 48" galv. iron pipe with brass cap on which is stamped a line with short cross mark and

Book I

175

Book I

175